

SECOND RE-ESTABLISHMENT
GCDB 400200

DOUGLAS COUNTY
SURVEYOR

Section corner common to Sections 27, 28, 33 and 34, Township 30 South, Range 2 East, W.M.

Found at the corner position, exposed 15 ins. in a mound of stones, the 2 ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1937, marked:

T30S R2E
S28 | S27
—+—
S33 | S34
1937

Bearing trees recorded by L. Carter of the GLO in 1937, found and measured to center at base:
Hemlock snag with a healed blaze brs. record; S 23° W, 20.2 ft.
Hemlock snag with scribe marks "S 28 BT" in partially healed blaze brs. N 23° W, 58.5 ft. Record;
57.9 ft.

Bearing trees recorded on 1st Re-establishment in 1978 found with healed double blazes and measured to center at lower blaze:
Hemlock now 18 ins. diam. brs. record; N 24° E, 68.7 ft.
S. fir now 29 ins. diam. brs. record; S 55° E, 44.9 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:
Hemlock 17 ins. diam. brs. S 27° W, 31.3 ft.
D. fir 6 ins. diam. brs. N 24½° W, 46.2 ft.

Corner lies approx. 50 ft. east of gravel road.

July 24, 2008

H. Durkee
B. Beeman

Roger R. Roberts
Jackson County Surveyor

P. – 148
V. – 15°30'

This corner report down loaded from Jackson Co. Surveyor's Office's web site 7/11/2012