

CORNER REPORT FORM

Section 14 Township 31S Range 4W
Douglas County Date 2-2012

CORNER DESIGNATION

500 500

Sec. COR 10-11-14-15

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

Markham 1959
DCSO 1998 CS file 664-12

Monument(s) & Accessories Found: (Condition and Source)

Fd 36" D. FIR S48°W 42¹/₂ FT GOOD SCAR
Fd 16" YEW S57°W 42¹/₂ FT GOOD SCAR
Fd 36" D. FIR S22°E 18° FT GOOD SCAR

Monument Detail

Sketch

FILED
Date: 7/30/2012 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 65/77-12

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

SET 5/8" I. ROD with 2 1/2 Alum CAP
marked Roseburg Resources Company

New Accessories

A 10" D. FIR BEAR'S N 14°W 10.2 FT scribed
T31 RD4 510 BT
A 12" D FIR BEARS NB2E 15.6 FT scribed
T31 RD4 511 BT

Location & Comments

Surveyor's Seal

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: B. KUAPP

Notes:

Witness:

C.S. File No 65/77-12

