

Date: 8/28/2012 By: JCThis survey consists of:
~~Map:~~ This corner report was downloaded
from the Jackson Co. Surveyor's
~~Narrative:~~ Office web site 8/28/2012Corner Rpt: C.S. 65/77-26**FIRST RE-ESTABLISHMENT**

GCDB 300300

**DOUGLAS COUNTY
SURVEYOR**

Section corner common to Sections 20, 21, 28 and 29 of Township 30 South, Range 3 East, W.M.

Found at corner position exposed 2 ins. in a mound of stones, the 2 ins. diam. galv. iron pipe with a 2½ ins. dia. brass cap set by the GLO in 1927 and marked:

T30S	R3E
S20	S21
S29	S28
1927	

Original bearing trees recorded by Herbert Raymond of the GLO in 1927, found and measured to center at base:

Fir snag with opened blaze revealing scribe marks "S28 BT" brs. record; S 82½° E, 53.5 ft.

Cedar sawed rotted stump brs. record; S 35° W, 35.6 ft.

Pine sawed rotted stump brs. record; N 43½° W, 45.5 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

D. fir 5 ins. diam. brs. N 34½° E, 7.5 ft.

D. fir 6 ins. diam. brs. S 21½° E, 16.1 ft.

D. fir 5 ins. diam. brs. S 22° W, 19.6 ft.

D. fir 5 ins. diam. brs. N 86¼° W, 26.3 ft.

Corner lies approx. 220 ft. east of spur road in old burn.

July 28, 2008

B. Beeman

H. Durkee

Roger R. Roberts

Jackson County Surveyor

P – 149

V – 16°05'