


FIRST RE-ESTABLISHMENT

GCDB 400300

DOUGLAS COUNTY SURVEYOR

Section corner common to Sections 21, 22, 27, and 28 of Township 30 South, Range 3 East, W.M.

Found at the corner position, exposed 7 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1928 and marked:



Original bearing trees recorded by H. Raymond of the GLO in 1928 found with healed blazes and measured to center at base;

- D. fir now 24 ins. diam. brs. record N29°E, 22.4 ft.
- D. fir now 15 ins. diam. brs N81°W, 21.3 ft. record ; 21.8 ft.
- D. fir rotted remains brs. record S71°E, 11.2 ft.
- D. fir snag brs. record S5½°W, 45.5 ft.

Marked new bearing trees 'CS''BT' and measured to center at lower blaze;

- W. fir 8 ins. diam. brs. S60¼°W, 41.1 ft.
- Hemlock 10 ins. diam. brs. S51°E, 44.5 ft.

Corner lies approx. 500 ft. S45°W of curve in gravel road on a 45% slope.

August 25, 2009

B. Beeman  
H. Durkee

Kerry K. Bradshaw  
Jackson County Surveyor

P. -194  
V. - 14°