

FILED

Date: 8/28/2012 By: JC

This survey consists of:

~~Map:~~ This corner report was downloaded from the Jackson Co. Surveyor's Office web site 8/28/2012

~~Narrative:~~
Corner Rpt: C.S. 65/77-28

FIRST RE-ESTABLISHMENT

GCDB 440400

DOUGLAS COUNTY
SURVEYOR

Quarter corner common to Sections 15 and 22 of Township 30 South, Range 3 East, W.1v.

Found at corner position, exposed 6 ins., the 2 ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by Herbert Raymond of the GLO in 1928 and marked:

T30S R3E
S15
¼ —
S22
1928

Original bearing trees found, both snags with healed blazes and measured to center at base:

Fir brs. N 68° E, 39.3 ft. Record; 38.3 ft.

Fir brs. S 71° E, 21.4 ft. Record; 2.0 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

Cedar 11 ins. diam. brs. N 64¼° E, 33.2 ft.

D. fir 13 ins. diam. brs. S 45½° E, 24.5 ft.

Yew 5 ins. diam. brs. N 13¼° W, 6.7.

S. pine 12 ins. diam. brs. S 88½° W, 59.0 ft.

Corner lies approx. 500 ft. east of logging spur road.

July 30, 2008

B. Beeman

H. Durkee

Roger R. Roberts

Jackson County Surveyor

P – 151

V – 15°20'

C.S. FILE: 65/77-28