

Date: 8/28/2012 By: JC

This survey consists of:

Map: This corner report was downloaded  
from the Jackson Co. Surveyor's  
Office web site 8/28/2012

~~Narrative~~  
Corner Rpt: C.S. 65/77-32

**SECOND RE-ESTABLISHMENT**

GCDB 700600

DOUGLAS COUNTY  
SURVEYOR

Section corner common to Sections 1 and 12 of Township 30 South, Range 3 East, and Sections 6 and 7 of Township 30 South, Range 4 East, W.M.

Found at the corner position, flush, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1927 and marked:

T30S	
R3E	R4E
S1	S6
S12	S7
1927	

Bearing trees recorded on 1<sup>st</sup> re-establishment in 1978 found with healed double blazes and measured to center at lower blaze;

D. fir now 35 ins. diam. brs. N20°E, 62.7 ft. record ; N19°E.

Hemlock now 24 ins. diam. brs. record S67°E, 88.2 ft.

D. fir now 46 ins. diam. brs. record S81°W, 54.5 ft.

W. fir snag brs. record N20°W, 6.0 ft.

Marked new bearing tree 'CS''BT' and measured to center at lower blaze;

W. pine 32 ins. diam. brs. N31½°W, 112.5 ft.

Corner lies approx. 3100 ft. south-westerly along trail from Hwy 62 and then approx. 100 ft west.

August 13, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -181

V. - 16°15'