

CORNER REPORT FORM

Section 10 Township 30S Range 8W

Douglas County Date 5-8-13

CORNER DESIGNATION

440500

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

DCSO SEPT 1964

Monument(s) & Accessories Found: (Condition and Source)

Fd DCSO BRASS CAP

17" D. FIR STUMP S39E 17.5 FT

24" MADROVA N10W 16.5 FT, visible Scribes, NO REC.

6" D. FIR DOWN & ROTTED

Monument Detail

Sketch

DCSO BRASS CAP

FILED

Date: 5/10/2013 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: C565/78-37

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

NONE

New Accessories

A 10" W. FIR S 9° E 14.5 FEET Scribed 1/4 S 15 BT

Location & Comments

ON STEEP EAST
FACING HILLSIDE
ON EDGE OF RIPRAP
UNIT 350'± EAST
OF LANDING @
END OF ROAD

Compass Declination

Firm/Agency: i.e. Engineering, Inc.



Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. Fromdahl

Surveyor's Seal



C.S. File No C5/78-37

EXP 12-31-14