

CORNER REPORT FORM

Section 2 Township 32S Range 8W
Douglas County Date 9. 2013

CORNER DESIGNATION

500700

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

DCSO 1967
BLM 1976-1977
M 83-26

Monument(s) & Accessories Found: (Condition and Source)

Fd 1967 DCSO BRASS CAP

44" D FIR S28W 198.
28" FIR S65E 27' (Now stump)(M 83-26 S62E)
36" FIR N35W 27'
32" fir NB2E 34'

Monument Detail

Sketch

FILED

Date: 10-16-2013 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/80-12

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

Set Alum post 2" EAST
RE TAG ALL TREES

Location & Comments

No New Trees
Due To Burn
July 2013

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. LEOPARD

Notes:

Witness: N. Fromdahl

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-14

C.S. File No 65/80-12