

CORNER REPORT FORM

Section 6 Township 32S Range 7W  
Douglas County Date 10-2013

CORNER DESIGNATION

100640

Condition Report only  
Not Found  
Renewed  
Unrecorded  
Surveyed In  
Referenced out

Previous Renewals/Surveys, etc:

DCSO 1965  
M83-25

Monument(s) & Accessories Found: (Condition and Source)

Fd DCSO BRASS CAP  
A 48" FIR STUMP 5' HIGH WITH BOLT SPIKE N80°W 12' FT  
A 4" + IN ROCK OUTCROP S58W 188 FT  
A 20" D FIR STUMP 8' HIGH BEARS S55°E 6 1/2 FT

Monument Detail

Sketch

COUNTY SURVEYORS OFFICE

T 32S

R 51 | 56 R  
B 7  
W Reset 1996 W  
1965

Monument Set (Procedures and Description)

FILED

Date: 10/21/2013 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt. CS 65/80-25

DOUGLAS COUNTY  
SURVEYOR

New Accessories

Set a lum. Post 20 North & 20 West of Cor  
Retag BT'S

Location & Comments

CORNER ON Steep  
North FACE 200' ±  
South of middle  
CR. ROAD  
AREA Burnt  
7/2013

Compass Declination 15 1/2

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.  
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. Fromdahl

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1634

EXP 12-31-14

C.S. File No 65/80-25