

CORNER REPORT FORM

Section 1 Township 32 Range BW  
Douglas County Date 10-2013

CORNER DESIGNATION

SW 1/16 51

Condition Report only

- NOT Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

M 83-25

Monument(s) & Accessories Found: (Condition and Source)

Fd 9/8" I. Red with Alum CAP  
22" fir N48°E 80 FT  
Burnt Hole S12W 32 3/4 FT

FILED

Date: 11/1/2013 By: J

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/80-36

DOUGLAS COUNTY  
SURVEYOR

Monument Detail

Sketch

T32S R3W 51  
SW 1/16  
1979  
LS 498

Monument Set (Procedures and Description)

New Accessories

Set Alum post 2° East & 2° South

Location & Comments

Retag Fir  
CORNER IN Baddy  
Burnt AREA  
Burnt 7/2013

Compass Declination 15 1/2

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.  
Roseburg, OR 97470

Party Chief: J. Leonard

Notes:

Witness: N. From Jah

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 16, 1978  
RONALD A. QUIMBY  
1634

EXP 12-31-14

C.S. File No 65/80-35