

CORNER REPORT FORM

Section 1 Township 32S Range 8W
Douglas County Date 10-2013

CORNER DESIGNATION

W $\frac{1}{16}$ $\frac{1}{12}$

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

BLM 1975
MBS-25

Monument(s) & Accessories Found: (Condition and Source)

Fd BLM BRASS CAP
24" fir N76°E 40[±] with SCAR
29" stump 5' HIGH S19E 5° FT GOOD SCAR

Monument Detail

Sketch

US Dept of Interior

W $\frac{1}{16}$ $\frac{S1}{S12}$

BLM

Monument Set (Procedures and Description)

FILED

Date: 11/1/2013 By: sc

This survey consists of:

Map: _____

Narrative: _____

Corner Pkt: C-65 80-37

DOUGLAS COUNTY
SURVEYOR

New Accessories

set Alum Post 2^o south
Re TAG TREES

Location & Comments

Corner is approx
200' south of
RAILROAD

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief:

Notes:

Witness:

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. GIMBY
1654

EXP 12-31-14

C.S. File No 65/80-37