

CORNER REPORT FORM

Section 1 Township 32S Range 8W
Douglas County Date 10-2013

CORNER DESIGNATION

C 1/4 51

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

M 83-25

Monument(s) & Accessories Found: (Condition and Source)

Fd 5/8" I. Rod with melted Alum cap Alongside
Burnt Root Hole & Burnt Log with burnt BT Tag
N 54 W 31° FT
Burnt Hole with burnt log 52° E 22° FT

Monument Detail

Sketch

FILED

Date: 11/1/2013 By: XC

This survey consists of:

Map: _____

Volume: _____

Corner Rpt: CS 65/80-39

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

SET Alum post 2° EAST & 2° South.

Location & Comments

CORNER IS NEAR
bottom of DRAW
Approx. 200' Below ROAD
BADLY BURNT
AREA 7-2013

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: N. Fomdahl

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-14

C.S. File No 65/80-39