

CORNER REPORT FORM

Section 24 Township 32S Range 8W
Douglas County Date 11-2013

CORNER DESIGNATION

640300

Condition Report only

- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

DCSO 1968

Monument(s) & Accessories Found: (Condition and Source)

FD County Surveyors Office
BRASS CAP

A 24" FIR STUMP S10W 15.2 FT Healed SCAR
A 32" FIR N27E 17 1/4 FT GOOD SCAR

UNRECORDED RT'S

A 18" FIR S88W 20 1/2 FT GOOD SCAR
A 14" FIR EAST 18 FT 1/15 Scribe

Both trees TAGGED 5/93 B.D RM

Monument Detail Sketch

County Surveyors Office
T 32S RBW

1/4 524
525

1968

FILED
Date: 11/25/2013 By: SC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 65/80-59

DOUGLAS COUNTY SURVEYOR

Monument Set (Procedures and Description)

New Accessories

ReTAG Trees
Alum POST 2° EAST

Location & Comments

Corner is approx
60' south of small
DRAW 125' EAST
OF ROAD along
Timber Line
AREA BURNED
8/2013

Compass Declination 15°
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St.
Roseburg, OR 97470
Party Chief: J. Leonard
Notes:
Witness: N. Fromdahl

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-14

C.S. File No 65/80-59