

CORNER REPORT FORM

Section 24 Township 32S Range 8W
Douglas County Date 11-2013

CORNER DESIGNATION

640400

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

SWENSON 1960 CS 51/63
BLM Resurvey 2007

Monument(s) & Accessories Found: (Condition and Source)

Ed BLM BRASS CAP

A 52" fir N18°E 52' FT Healed BLAZE
A 36" Pine Stump S78W 49.5 FT
A 26" fir S34E 25' FT Healed BLAZE

Monument Detail

Sketch

U.S. Department of Interior
BUREAU OF LAND MANAGEMENT
T 32S R 8W
1/4 S13
 S24
 2007

FILED
Date: 11/25/2013 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/80-60

Monument Set (Procedures and Description)

DOUGLAS COUNTY
SURVEYOR

New Accessories

set Alum post 2° west
Retag Trees

Location & Comments

AREA BURNED
8/2013

Compass Declination 15

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. Leonard

Notes:

Witness: N. Fromdahl

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1634

EXP 12-31-14

C.S. File No 65/80-60