

CORNER REPORT FORM

Section 24 Township 32S Range 8W

Douglas County

Date 11-2009

CORNER DESIGNATION

2013

Condition Report only

- NOT Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

700300

Previous Renewals/Surveys, etc:

Hull L S #901 M 111-4
Estabrook 2003 CS 45/45-24 BLM Resurvey 2007

Monument(s) & Accessories Found: (Condition and Source)

BLM BRASS CAP
 A 10" MADRONA N16°E 17⁸ FT V/S Scribes
 A 12" FIR S63E 6⁹ FT Healed BLAZE
 A 12" FIR S56W 6⁹ FT " "
 A 14" FIR N4W 45⁵ FT " "

Monument Detail

Sketch

U.S. DEPARTMENT OF INTERIOR
BUREAU OF LAND MANAGEMENT

T32S
 RBW | RTW
 524 | 519
 525 | 520
 2007

FILED

Date: 11/25/2013 By: JC
 This survey consists of:
 Map: _____
 Narrative: _____
 Corner Rpt: CS 65/80-6L

Monument Set (Procedures and Description)

DOUGLAS COUNTY
SURVEYOR

New Accessories

Set Alum Post 20 West
Retag Trees

Location & Comments

AREA BURNED
8-2013

Compass Declination 15

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. Leonard

Notes:

Witness: N. Fromdahl

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1634

EXP 12-31-14

C.S. File No 65/80-6L