

FILED

Date: 11/10/2015 By: X
This survey consists of:
Map: CS 65/88-11
Narrative: 295
Corner Rpt: _____

CORNER REPORT FORM

Section 12 DA Township 27 Range 6
Douglas County Date 11-2015
PLSS Number _____

DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

N.A.

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

SET BY ODOT

Monument(s) & Accessories Found: (Condition and Source)

ODOT YELLOW CAP ON IRON ROD
DESTROYED BY CONSTRUCTION OF CURB RETURN
AT THE NORTH RETURN OF SOUTH ENTRANCE OF
EMERALD STREET. ODOT R/W 2467+00 44' RT

Monument Detail

Sketch

Monument Set (Procedures and Description)

SET A 1" BRASS CAP IN PLASTIC SLEEVE STAMPED
"ODOT" CAP SET BY COORDINATES SUPPLIED BY
MSA ENGINEERS AS SURVEYED BY LANDMARK
SURVEYING

New Accessories

Surveyor's Seal

Location & Comments

N. CURB RETURN IN
SOUTH ENTRANCE OF
EMERALD ST.

Compass Declination

Firm/Agency: I.e. Engineering, Inc.

Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief:

Notes:

Witness:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Gimby

OREGON
JULY 14, 1978
RONALD A. GIMBY
1654

EXP 12-31-16

C.S. File 65/88-11