

FILED

Date: 9/30/2015 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/89-33

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 12 Township 31S Range 3W

Douglas County

Date 8/2015

PLSS Number
640520

CORNER DESIGNATION

CS 1/16 S12

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Set by MARKHAM Nov. 1959
CS 42/392

Monument(s) & Accessories Found: (Condition and Source)

PIPE NOT FD.

BADLY

A 14 LAUREL S36°W 17.4 FT BURNT OUT FACE WITH BT
TAG BY MARKHAM ADDED SPIKE SIDE & CENTER
BURNT OUT STUMP S23°E 37.0 FT

Monument Detail

Sketch

Monument Set (Procedures and Description)

SET 5/8" I. ROD & yellow PLASTIC CAP STANDARD IE
ENGINEERING BRING & DISTANCE FROM LAUREL DIST.
CHECKS TO BURNT OUT STUMP

New Accessories

9" D. FIR N52W 20 FT SCRIBED CS 1/16 S12 BT
SPIKE SIDE & CENTER
SET ALUM POST 2° SOUTH & 2° EAST

Surveyor's Seal

Location & Comments

HAND HOLD L&T
LONG
N 42° 53' 24"
W 123° 00' 12"
AREA BADLY BURNT
8/2015

Compass Declination 15 1/2° E
Firm/Agency: I.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. Frowdahl

Notes:

Witness: R. OLSON

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1054

EXP 12-31-16

C.S. File 65/89-33