

OREGON CORNER RESTORATION FORM

FILED

Date: 6/5/2016 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/93-6

Section 32 Township 23 South, Range 6 West
County Douglas Date 31 January 2016

DOUGLAS COUNTY
SURVEYOR

Corner Description

Section Corner

Sections 31, 32 T23S, R6W
Sections 5, 6 T24S, R6W

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found BLM brass cap dated 1957
17" Hemlock stump bears S 30° W 11.2' – rotted face
40" D. Fir metal capped stump bears N 74° W 37.6' – healed face
13" Hemlock stump bears S 20° W 20.6' – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

Corner falls in recently logged area.
No new accessories established.
Set 60D nail at side center of all bearing tree stumps.
Added galvanized sheet metal cap to NW bearing tree stump as noted above.

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness Cody Kievit

Surveyor's Seal



RENEWS: 12-31-2016

C.S. FILE 65/93-6