

FILED

Date: 7-18-2018 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/101-40

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 8,9 Township 31S Range 6W
Douglas County Date 01/29/18
PLSS Number 300540

CORNER DESIGNATION

1/4 S8 | S9

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Oct 1980 - Oct. 1981 BLM resurvey (DCSO records Vol. 45, Pages 17305-06)

Monument(s) & Accessories Found: (Condition and Source)

Found 2-1/2" BLM brass cap on a 2-1/2" iron pipe from which a:
9" (now 15") fir with healed face bears S31°E 7.3'
5" (now 10") fir with healed face bears N71°W 21.1'

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

7" fir scribed "X BT" in double face bears N5°W 5.9'
6" fir scribed "X BT" in double face bears S71°E 24.4'

Surveyor's Seal

Location & Comments

OREGON COORDINATE REFERENCE SYSTEM, COTTAGE GROVE - CANYONVILLE ZONE, NAD 88-(2011), EPOCH 2010 PER GPS OBSERVATION HOLDING NGS CORS STATIONS "RSBG" & "DDSN"
Lat. N42°53'00.27.9335"
Lon. W123°25'36.5665"

Compass Declination 15°
Firm/Agency: Land Mark Surveying, Inc.
Address: P.O. Box 13
Roseburg, OR 97470
Party Chief: Bartt Heichel
Notes: _____
Witness: Anthony Welch



Mark A. Heimburger
OREGON
JULY 18, 1989
MARK A. HEIMBURGER
2287

Renews 06/30/19

C.S. File 65/101-40