

FILED

Date: 7-18-2014 By: SC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/101-47

DOUGLAS COUNTY  
SURVEYOR

CORNER REPORT FORM

Section 4 Township 21S Range 10W  
Douglas County Date 4-30-16  
PLSS Number 340627

CORNER DESIGNATION

Property corner

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

M91-24

Monument(s) & Accessories Found: (Condition and Source)

FND 2 1/2" BRASS CAP DOWN OS IN gravel Road.  
STAMPED "PLS 497" IN Good condition  
SOUTH 0°40'41"E 874.71' From C 1/4 OF Section 10 T21S R10W

Monument Detail

Sketch

Original Bearing tree 36" Hemlock now  
a rotten stump Nail side center - Has Fallen  
out of stump lies on ground Adjacent to stump.  
original 18" Bearing tree not Found.

Monument Set (Procedures and Description)


New Accessories

New Bearing tree:  
11" Hemlock Bears S21°E 35±' Faced Tagged Nail side center } tagged  
13" Fir Bears S74°W 14' Faced tagged nail side center. } and  
blazed

Surveyor's Seal

Location & Comments

Compass Declination 14°  
Firm/Agency: Stuntz Assoc Eng & Forestry  
Address: PO Box 118  
Cross Bay, OR 97420  
Party Chief: Danny Dean  
Notes: Ashley Miller  
Witness: \_\_\_\_\_



RENEWS:

C.S. File 65/101-47