

FILED

Date: 5/14/2019 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 63/102-40

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 25 Township 23S Range 8W
Douglas County Date 4-2019
PLSS Number 600232

CORNER DESIGNATION

LINE TREE



Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

BLM Resurvey 1964 Vol 32 PG. 13537

Monument(s) & Accessories Found: (Condition and Source)

ORIG. LINE TREE 55" D. FIR NOW 55" D. FIR
STUMP

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

REFERENCE'S TO LINE TREE
14" FIR N28°E 13.6 FT scribed 525 BT
11" FIR S53°W 17.7 FT scribed 526 BT

Surveyor's Seal

Location & Comments

Compass Declination 15 1/2° E



Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: M Fromdahl

Notes:

Witness: R. Heiche



C.S. File 65/102-40
EXP 12-31-20