

FILED

Date: 5/14/2019 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS65/102-41

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 25 Township 23S Range 8W
Douglas County Date 4-2019
PLSS Number 600240

CORNER DESIGNATION

1/4 COR 26/25



Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

BLM RESURVEY 1964 Vol 32 PG. 13537-38
Weatherly 1980 CS 58/247 BLM Resurvey 1985 Vol 4B PG
Monument(s) & Accessories Found: (Condition and Source) 18238-39

BLM BRASS CAP

28" CEDAR S33°E 24 FT GOOD SCAR

21" CEDAR S28°W 39 FT " "

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

15" Hemlock S60°E 152 FT scribed 1/4 525 BT

21" Hemlock N43°W 153 FT scribed 1/4 526 BT

Surveyor's Seal



Location & Comments

Compass Declination 15'5"E
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. Fromdahl

Notes:

Witness: R. Heichel



65/12-31-20
C.S. File 65/102-41