

FILED
Date: 2/11/2020 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/104-31

CORNER REPORT FORM

Section 14 Township 21S Range 7W
Douglas County Date 1-2020
PLSS Number
400500

DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

Sec Cor 9/10
16/15

<input type="checkbox"/>	Condition Report only
<input type="checkbox"/>	Not Found
<input checked="" type="checkbox"/>	Renewed
<input type="checkbox"/>	Unrecorded
<input type="checkbox"/>	Surveyed In
<input type="checkbox"/>	Referenced out

Previous Renewals/Surveys, etc:

BLM RESURVEY 1963 Vol 32 PGS 13136-7

Monument(s) & Accessories Found: (Condition and Source)

BLM BRASS CAP
22" FIR N5°E 11 $\frac{1}{2}$ FT GOOD SCAR
23" FIR SB $\frac{1}{2}$ W 13 $\frac{1}{2}$ FT GOOD SCAR

Monument Detail

U.S. CADASTRAL Sketch SURVEY
PENALTY \$250 FOR REMOVAL
T21S R9W

59 | 510
516 | 515
1963

BUREAU OF LAND MANAGEMENT

Monument Set (Procedures and Description)

New Accessories



22" Hemlock N67°W 27 $\frac{1}{2}$ FT scribed T21S R9W 59 FT
6" W. Fir S43°W 8 $\frac{1}{2}$ FT scribed T21S R9W 516 FT

Surveyor's Seal

Location & Comments

Compass Declination 15 $\frac{1}{2}$ °E
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: J. Olden
Notes:
Witness: L. Heddens



EXP 12-31-20

C.S. File 65/104-31