

FILED

Date: 3-18-2020 By: SC

This survey consists of:

Map: _____

Narrative: _____
Corner Rpt: CS 65/104-42

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 10 Township 31S Range 5W
Douglas County Date 1-2020
PLSS Number
400500

CORNER DESIGNATION

9/10
16/15

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Temp/10 1957 CS 42/303 KING 1960 CS 51/56
BLM RESURVEY 1972-73 Vol 38 pg 15605

Monument(s) & Accessories Found: (Condition and Source)

BLM BRASS CAP
58" FIR N12E 43 1/2 FT BRK scribed
50" FIR S70 1/2 E 37 1/2 FT GOOD SCAR.

Monument Detail

Sketch

U.S. DEPT. OF THE INTERIOR
T 31S R 5W
59 | 510
516 | 515

BUREAU OF LAND MANAGEMENT

Monument Set (Procedures and Description)

New Accessories

5/8" I. ROD S30W 6 3/4 FT Both have yellow plastic caps
5/8" I. ROD N78W 5 1/2 FT Stamped re engineering

Alum posts alongside Surveyor's Seal

Location & Comments

AREA BADLY
BURNED 2019

Compass Declination 15 1/2° E
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: R. Heichel
Notes:
Witness: J Ogden

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1954

EXP 12-31-20

C.S. File 65/104-42