

FILED

Date: 3-18-2020 By: XC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/104-49

DOUGLAS COUNTY  
SURVEYOR

CORNER REPORT FORM

Section 17 Township 31S Range 5W  
Douglas County Date 2-2020  
PLSS Number 307500

CORNER DESIGNATION

SEC COR B/9  
17/16

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

KING, 1959 CS 51/56 DCSO 1964 CS 54/25-19 BLM 1972-73  
BLM RESURVEY 1966-1968 Vol 35 PG. 1436B Vol 38  
Monument(s) & Accessories Found: (Condition and Source) PG 15666-87

BLM BRASS CAP

22" W. FIR S 41 1/2° W 10' FT GOOD SCAR  
70" FIR N 29° W 38' FT VIS BARK SCRIBES  
40" FIR N 85° E 56' FT GOOD SCAR

Monument Detail

Sketch

U.S. DEPT. OF INTERIOR  
UNLAWFUL TO DISTURB  
T 31S R 5W

58 | 59  
517 | 516  
1966

Monument Set (Procedures and Description)

CADASTRAL SURVEY  
BUR OF LAND MANAGEMENT

New Accessories

Alum Posts 2' EAST & 2' NORTH

Surveyor's Seal

Location & Comments

AREA BURNT  
2019

Compass Declination 15 1/2° E

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. Fromdahl

Notes:

Witness: L. Heddens

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Ronald A. Quimby  
OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXP 12-31-20

C.S. File 65/104-49