

GOVERNMENT CORNER RESTORATION FORM

Date: 3-16-98 By: X

This survey consists of: \_\_\_\_\_

Township 25S Range 7W Sec: 15

County DOUGLAS Map: \_\_\_\_\_

State OR Date 3-10-98

No. \_\_\_\_\_ Narrative: \_\_\_\_\_

Corner Rpt: 66/2-2

Corner Designation

$\frac{1}{4}$   $\frac{S 15}{S 22}$

DOUGLAS COUNTY SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals 1968 BLM

Monument(s) Found: (Condition and Source)

3 1/2" DIA. BRASS CAPENA 2 1/2"  
20 IRON PIPE PROTRUSIONS  
8" ABOVE GROUND. (1968)

U.S. DEPT. OF THE INTERIOR  
T25S R7W

$\frac{1}{4}$   $\frac{S 15}{S 22}$   
1968

BUR. OF LAND MANAGEMENT

Accessories Found:

18" NOW 36" DIA 2 FT HIGH OAL STUMP  
WITH EVIDENCE OF A PREVIOUSLY OPENED BLAZE  
NO SCRIBING VISIBLE, MAIN TRUNK IS ON  
GROUND. BEARS N 72 3/4° W, 237.6 FT.  
CAGREES WITH REC.) OBT

19" NOW 32" DIA 2 FT HIGH D. FIR STUMP  
WITH A FULLY HEALED SINGLE BLAZE,  
BEARS N 72 1/2° E, 155.1 FT 1968

25" NOW 57" DIA. 2 FT HIGH D. FIR STUMP  
WITH A FULLY HEALED SINGLE BLAZE  
RECORD BEARING "S 49 1/2° W, 208.4 FT"  
NOT CHECKED. 1968

