

GOVERNMENT CORNER RESTORATION FORM

Date: 4-6-1998 By: X

This survey consists of:

Township 2LS Range 11W Sec. 5 County DOUGLAS Map: _____

State OR Date 3-18-98 No. _____

Narrative: _____

Corner Rpt: 66/2-7

Corner Designation

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

$\frac{1}{4} \frac{55}{58}$

MONUMENT DETAIL

Previous Renewals 1967 DC50

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 1 1/2"
OD IRON PIPE PROTRUS
4" ASBE GROUND. 1267

COUNTY SURVEYORS OFFICE
T21S

$\frac{1}{4} \frac{55}{58}$

R11W
1967

Accessories Found:

18" NOW 27" DIA. 7 FT TALL STUMP THAT HAS RESPROUTED
WITH A HEALED BLAZE, BEARS S21°E, 57.3 FT
(AGRES WITH REC.) 1967
18" NOW 21" DIA ROTTED DOUBLE TRUNKED CEDAR
STUMP, NO BLAZE OR SCRIBING VISIBLE BEARS N23°E,
46.7 FT TO WESTERLY TRUNK (AGRES WITH REC.) 1967

