

GOVERNMENT CORNER RESTORATION FORM

Date: 4-23-1999 By: JC

This survey consists of:

Township 27S Range 7W Sec. 2 County DOUGLAS

Map: _____

State OR Date 1-25-1999 No. 540600.012

Narrative: _____

Corner Rpt: 66/8-5

Corner Designation

$\frac{1}{4} \frac{S2}{S11}$

PI # 540600

Previous Renewals 1960 DC50

DOUGLAS COUNTY SURVEYOR

- ____ Condition Report Only
- ____ Not Found
- Renewed
- ____ Unrecorded
- ____ Surveyed In
- ____ Referenced Out

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A
1 1/2" O.D. IRON PIPE IS
FOUND KNOCKED OVER AND
BENT. 1960

COUNTY SURVEYORS OFFICE
T27S R7W

NOTE BULL DOZER HAS SCARRED
PART OF BRASS CAP

$\frac{1}{4} \frac{S2}{S11}$

196

Accessories Found:

BRG + DIST TAKE FROM PLUMB POSITION OF I.P.
NO OBJ'S FOUND

7" NOW 29" DIA P. PINE WITH A FULLY HEALED
SINGLE BLAZE BEARS N34°E, 177.8 FT
(AGREES WITH RECORD) 1960

7" NOW 20" DIA. P. PINE WITH A FULLY HEALED
SINGLE BLAZE BEARS S55°W, 126.8 FT
(AGREES WITH REC.) 1960

