

GOVERNMENT CORNER RESTORATION FORM

Date: 4-23-1999 By: JC

Township 30S Range 4W Sec. 10

County DOUGLAS This survey consists of:

State OR Date 3-24-99

No. 440500.034 Narrative: _____

Corner Rpt: 66/B-24

Corner Designation

$\frac{1}{4} \frac{S10}{S15}$

DOUGLAS COUNTY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals 1989, 1992 + 1963 DCSO

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON 1 1/2"
P.O. IRON PIPE PROTRUSIONS
6" ABOVE GROUND (1963)

COUNTY SURVEYORS OFFICE
T 30S

$\frac{1}{4} \frac{S10}{S15}$ R
4
W

1963

Accessories Found:

15" NOW 27" DIA. W/OAK WITH PREVIOUSLY OPENED
ROTTED BLAZES, NO SCRIBING VISIBLE, BEARS
N 78 1/4° W, 36.3 FT (AGREES WITH RENEW.) OBT

10" NOW 29" DIA B.OAK WITH A FULLY HEALED
DOUBLE BLAZE BEARS S 19° W, 43.0 FT
(R.C.L. PER 1963 REN. S 19° W, 42.2 FT) OBT

✓✓

