

GOVERNMENT CORNER RESTORATION FORM

Date: 4-23-1999 By: JC

This survey consists of:

Township 29S Range 7W Sec. 14 County DOUGLAS Map: \_\_\_\_\_

State OREGON Date 04/13/99 No. 500440.021 Narrative: \_\_\_\_\_

Corner Rpt: 106/B-25

Corner Designation

1/4  
S15 | S14

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals 1957 BLM RESURVEY, 1962 DCSO RENEWAL

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

FROM THE 1957 BLM RESURVEY A 2 1/2 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 1 INCH O.D. IRON PIPE, FIRMLY SET AND PROTRUDING APPROXIMATELY 2 INCHES ABOVE GROUND. SOME SMALL STONES ARE SET FLUSH WITH SOIL AROUND PERIMETER OF BRASS CAP.

U.S. GENERAL LAND OFFICE

T29S R7W

1/4

S15 | S14

1957

Accessories Found:

NO EVIDENCE OF ORIGINAL BEARING TREES IS FOUND.

FROM THE 1957 BLM RESURVEY, A FIR 28" DIAM. NOW A 47 INCH D.B.H. DOUGLAS FIR BEARS S11 1/2°W, 158 2 FEET DISTANT (AS PER 1962 DCSO RENEWAL). TREE HAS FULLY HEALED SINGLE BLAZE.

FROM THE 1962 D.C.S.O. RENEWAL A 3/4 INCH DIAMETER IRON ROD FIRMLY SET, FLUSH WITH GROUND SURFACE BEARS WEST 59 3 FEET DISTANT (AS PER RECORD). NORTH-SOUTH FENCE LINE RUNNING THROUGH THIS BEARING OBJECT LOCATION HAS BEEN REMOVED.

C ✓

