

GOVERNMENT CORNER RESTORATION FORM

Date: 11/3/1999 By: SC

This survey consists of:


Township 28S Range 5W Sec. 8 County DOUGLAS Map: _____

State OK Date 9-8-99 No. 300500.018 Narrative: _____

Corner Rpt: 66/12-27

* Corner Designation

(NOTE POSITION OF
1/4 S8/S9 USED IN
SETTING THIS POSITION
IN 1945 WAS FOUND TO BE
IN ERROR PER 1961 OCSO RENEWAL



Previous Renewals 1945 + 1961 OCSO

Monument(s) Found: (Condition and Source)

1/2" O.D. IRON PIPE
FLUSH WITH GROUND 1945

Accessories Found:

8" DIA FORKED TRUNK NOW 24" DIA SINGLE TRUNK
W/OAK WITH A FULLY HEALED SINGLE BLAZE, BEARS
EAST, 33.2 FT (REC. N 86° E, 33.2 FT) 1945

10" NOW 19" DIA W/OAK WITH A FULLY HEALED
DOUBLE BLAZE, BEARS N 88° W, 35.8 FT (AGREES
WITH REC.) 1961

OBT'S LOOKED FOR NOT FOUND

- DOUGLAS COUNTY SURVEY ONLY
- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

N/A

RENEWAL

Monument Set (Procedure and Description)

NONE

Monument Detail

N/A

New Accessories

NONE

Sketch of Monument, Accessories, and General Area

Location & Comments

IRON PIPE LIES AT THE INTERSECTION OF FENCE LINES RUNNING E-W + S. 10 FT WEST OF N-S GRAVEL ROAD CL.

Comp. Declin. 17 3/4° E
Agency DCSO
Party Chief RANDALL W. SMITH
Notekeeper [Signature]
Witnesses STEPHEN J. FLAUS

Address

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]
EXPIRES 6-30-2000

OREGON
JULY 25, 1990
RANDALL W. SMITH
2489

