

50260-009

1-20-00

T275 R4W SE COR SEC 34

S34 S35 RANDALL W SMITH

STEPHEN J FLAUSC

FD BLM BRASS CAP / IRON PIPE
PROTRUDS 9" OUT OF GROUND

AT FENCE CORNER WITH FENCE
LINES RUNNING NORTH + WEST

35" NOW 40" DIA 4 FT HIGH

D. FIR STUMP WITH A HEALED BLAZE
BEARS N60°W 21.5 FT

(REC N60°W 20.5 TO BLAZE) OBT

20" NOW 25" DIA 1 FT HIGH D. FIR

STUMP WITH A HEALED BLAZE BEARS
S55°E 15.4 FT (REC S55°E 13.9 FT

TO BLAZE) OBT

13" CEDAR NOW BARELY ROTTED

STUMP NO SCRIBING VIS. FOUND NEAR

REC "N 59°E 73.3 FT" 1958

13" NOW 18" DIA CEDAR WITH

SCRIBING VIS. "T275 R4W S34 S35 BT"

BEARS N 29 3/4° W 39.1 FT 1958

6" NOW 5" 3 FT HIGH CEDAR STUMP

FD NEAR REC "N 36 1/2° E 136.8 FT 1967

BLM BC/IP CC 53152 BEARS WEST, 39.7 FT

NEW 9" CEDAR DOUBLE BLAZED AND

SCRIBED "T275 R4W S35 S35 BT"

BEARS N 81° E / 55.2 FT

6/6/14-6
DARLING CO
MOUNTAIN VIEW
U.S. FILE NO

No. 312

FILED FEB 8 2000