

No. 312

FILED FEB 17 2000

RANDALL W SMITH  
STEPHEN J FRAUSE

Z-10-00

CORNERS LOOKED FOR

NOT FOUND IN  
T27S R4W

✓	NE COR DLC 50	050010
✓	ESE COR DLC 50	050060
✓	INT L COR DLC 50	050050
✓	SE COR DLC 50	050040
✓	SW COR DLC 50	050030
✓	NW COR DLC 50	050020

NE COR DLC 51 051010 ✓

ESE COR DLC 51 051060 ✓

INT L COR DLC 51 051050 ✓

SE COR DLC 51 051040 ✓

SW COR DLC 51 051030 ✓

NW COR DLC 52 052020 ✓

CORNERS FOUND OK IN

T27S R4W

S 1/4 SEC 32 240100 ✓

NE COR DLC 52 052010 ✓

S 1/16 COR 32 | 33 300120 -

28 | 27 1/4 34 | 35 500110 ✓

33 | 34 400200 ✓ 1/4 34 | 35 500110 ✓

SEE BACK

C.S. File No. 66/14-21

ALSO  
66/14-21  
L. CARING COPY  
TACOMA, WA 98421

CORNER FOUND OF

T28S R4W

N<sup>1</sup>/<sub>4</sub> S5

240.700

✓

(241100)

CS 66/14 - 21