

10-10-00

FILED OCT 30 2000 050020

T265 RAW NW COR DLG 50
CONDITION REPORT ON CORNER POSITION
DETERMINED IN 1981 BY

B.A. SHANKS

RANDALL W SMITH STEPHEN J FLAUSK

FD 1981 BRASS CAP IRON PIPE
10" BELOW GROUND.

10" B.OAK NOW BADLY ROTTED
3 FT HIGH OAK SKEEL BEARS
S 45° E, 15.8 FT (AGREES WITH
ORIG. REC.)

7" B.OAK NOTED AS A 36" MAPLE
IN 1981 NOW 38" DIA HOLLOWED
OUT AND ROTTED MAPLE BEARS

N 34° W, 47.0 FT (ORIG REC N 30° W
49.5', 1981 REC "N 30° W 42.0')

10" NOW 12" W. OAK WITH A FULLY
HEALED SINGLE BLAZE BEARS
S 85 1/2° E, 96.4 FT (1981)

14" NOW 16" ALONG WITH BARK
-SCRIBING "T265 RAW NWC (1980)
DLG 50 BT" BEARS N 40° W, 75.2 FT
CORNER IS APPROX 1/2 FT
SW OF SW CORNER OF BRIDGE

OVER CREEK. G.S. FILE NO. 66/16-49A

(W/2 RETAG 1981 BT'S)

L. DARLING CORP.
TACOMA, WASH. USA

Plot in the Rain
WEATHERPROOF

No. 302

GPS T26S R4W

NW DCC 50

050020

R101922A

~~26 27 33 34~~

R101923A

~~27 28
33 34~~

26-4 400200

SW 27

FILED OCT 30 2000

FILED

~~Date: _____ By: _____~~

~~This survey consists of:~~

~~Map: _____~~

~~Notes: _____~~

~~Corner Rpt: _____~~

DOUGLAS COUNTY
SURVEYOR

C.S. File No. 66/16-49B

J. L. DARLING CORP.
TACOMA, WASH. U.S.A.

"Rite in the Rain"
WEATHERPROOF

No. 302

Point Properties

North: 594913.892 USft
East: 1292549.801 USft
Altitude (MSL): 734.057 ft

Summary | 95% Precisions | DOPs

Date: 10/18/2000
Time: 11:53:36 000 am

Vertex:
Position: Average of 6
Horiz. Precision: 9.7 USft
Status: 3D Differential
Filename: R101822A.cor

Feature Properties

First < > Last Delete

Point feature: CONTROL MONUMENT

Attribute Name	Value
NAME	NW DLC 50
MON TYPE	BC IP

Summary | Attributes | 95% Precisions

Positions: 6
Std Deviation: 4.1 USft

Filename: R101822A.cor
Status... New
Offset... <None>