

8-10-01

FILED JAN 16 2001

TZ85 RGW Y4531/S32

RANDALL W SMITH, STEPHEN J FLAVER

FD 1958 DCSO BRASS CAP/IRON

PIPE, PROTRUDS 12" OUT OF
GROUND. BE/1P IS AT A

FENCE CORNER WITH FENCE LINE
RUNNING SOUTH AND EAST

20" NOW 27" DIA 12 FT TALL

ROTTED OAK SNAG PREVIOUSLY

OPENED UNHEALED BLAZE

SCRIBING VISIBLE "S" BEARS

N67°E, 54.1 FT (AGREES WITH ORIG REC)

14" NOW 25" DIA DIFIR WITH A

FULLY HEALED SINGLE BLAZE

BEARS N25°E, 50.9 FT (AGREES

WITH 1958 REC.) 1958

15" NOW 24" DIA DIFIR WITH A

FULLY HEALED SINGLE BLAZE

BEARS N29 1/4°W, 40.9 FT (AGREES

WITH 1987 BLIN REC.) 1958

NEW "

11" DIA. DIFIR DOUBLE BLAZED AND

SCRIBED "Y4531CSBT" BEARS, S60°W, 25.0 FT

7" DIA MADRONE SINGLE BLAZED AND

SCRIBED "Y4532CSBT" BEARS, S12 1/2°E, 26.5 FT

COMPRESS DECL. 1774°E

C.S. File No. 666/19-6