

GPS R022620A

2-26-01

T 265 RSW 1/4 511

517

NW COR OLL 39

FILED MAR 1 2001

MC RT BANK

RANDALL W SMITH, STEPHEN J FLAUSK
FD 1954 NCSO BRASS CAP IRON PIPE
BADLY BENT PROTRUDES 8" OUT OF
GROUND.

11" DIA W. OAK WITH A
FULLY HEADED DOUBLE BLAZED
BEARS S 79 1/4° E, 332.3 FT (1954)

NO OTHER BT'S FOUND
NEW

19" DIA W. OAK DOUBLE BLAZED
AND SCRIBED "YAS 115 BT"
BEARS N 54 1/2° E, 458.2 FT
5/8" IRON ROD PER 1995 M 99-55
BEARS S 88° 1/4° E 637.3 FT
(WESTERLY RW PIN) ON DCL
LINE.

27" DIA W. OAK DOUBLE BLAZED
AND SCRIBED "YAS 11 CS BT"
BEARS N 43 1/4° E, 325.6 FT
1954 BCLIP STRAIGHTENED
AND RETURNED TO PLUMB POSITION
PROTRUDES 2" ABOVE GROUND.
COMPASS DECL 17 3/4° E

J. L. DARLING CORP
TACOMA WASH. U.S.A.

"Rite in the Rain"
WEATHERPROOF

No. 302

C.S. File No. 66/19-45