

8-16-01

FILED AUG 23 2001

T225 RGW Y4 S4 | S3

RANDALL W. SMITH STEPHEN J. FLAUS

FO 1214 3/4" I.D. IRON PIPE

PROTRUDES 4" OUT OF GROUND

1961 DCSO BRASS CAP IRON

PIPE PROTRUDES 10" OUT OF

GROUND ALONG WESTERLY EDGE
OF 3/4" I.P.

24" NOW 48" DIA 6 FT HIGH ROTTEN
AND BURNT D. FIR STUMP PREVIOUSLY

OPENED WITH EVIDENCE OF OLD

BLAZE ILLEGIBLE REVERSE

SCRIBING AND CHAINING NOTCH

VISIBLE, BEARS S85°W, 54.1 FT

(REC S83°W, 54.1 FT) (OBT)

ORIG. SE MAPLE NOT FOUND

6" NOW 13" DIA. B. OAK WITH

A FULLY HEALED BLAZE, BEARS

N23°E, 7.2 FT (1961)

4" NOW 14" DIA 6" HIGH D. FIR

STUMP NO BLAZE VISIBLE

BEARS N77 1/2°W, 35.2 FT (1961)

COMPASS DECL. 17 3/4° E

(ON BACK) C.S. File No. 66/21-35

NEW

20" DIA. MAPLE BEHIND A LEARNING
10" BLOAK DOUBLE BLAZED
AND SCRIBED "Y4S4CSBT"

BEARS N 40° W, 22.2 FT

9" DIA. D. FIR DOUBLE BLAZED
AND SCRIBED "Y4S4CSBT"

BEARS N 83° W, 27.6 FT

25" DIA. D. FIR DOUBLE BLAZED

AND SCRIBED "Y4S3CSBT"

BEARS S 30 1/2° E, 15.6 FT

66/21-35