

6-25-62

PI #050650

WITNESS COR.

FILED JUN 26 2002

T233 R7W SW COR DLG 50

SE COR DLG 53

RANDALL W SMITH STEPHEN J FLAUSO

FD 1965 DCSO BRASS CAP / IRON

PIPE PROTRUDING 6" OUT OF

GROUND AND TIPPED OVER 1921

3/4" BY 29" LONG IRON PIPE 7"

BELOW GROUND PLUMB POSITION

FALLS IN N'LY RUNNING

FENCE LINE. 1965 DCSO BC/IP

SET IN ERROR BEARS

N66°W, 3.4 FT.

FROM 1921 POSITION (VOL 3 PG 90)

10" NOW CLUSTER OF W. OAK

WITH A PREVIOUSLY OPENED UNHEALED

BLAZE ON 14" DIA. NW'LY TRUNK

CENTER OF OAK CLUSTER BEARS

S66°E, 27.0 FT CENTER OF

NW'LY TRUNK S66°E, 25.3 FT (1921)

12" NOW 17" DIA W. OAK

WITH A FULLY HEALED BLAZE

BEARS S23 1/2°W, 40.0 FT (1921)

10" B. OAK NOW 11" DIA W. OAK

WITH A FULLY HEALED DOUBLE

BLAZE BEARS N53°E, 14.9 FT (1965)

LOW BACK G.S. File No 66/34-13

615 R062523A

OFFSET EAST 50 FT

20" B. OAK NOW 25" D/A. W. OAK
WITH A FULLY HEALED SINGLE
BLAZE, BEARS N10 1/2° W, 30.0 FT

1965 BC/IP REMOVED AND A
5/8" BY 30" LONG IRON ROD WITH
DCSO PLASTIC CAP SET AT ITS
POSITION FLUSH WITH GROUND.

AT PLUMB POSITION OF 1921
I.P. 1965 BC/IP IS SET
AND STAMPING ADDED "RESET
2002" PROTRUDES 10" OUT OF
GROUND. 1921 I.P. SET ALONG
NORTH EDGE OF BC/IP PROTRUDES
8" OUT OF GROUND

COUNTY SURVEYORS OFFICE

T 23 S

R 7 W

S 8 E

W 6

100 FT

SE 1/4

TO COR

53

RESET 2002

1965

COMPASS DECL. 17 1/4° E

66/24-13