

26-SW
COR ID 700400

9-19-2002

FILED SEP 20 2002

R	S13	S18	R
S			↑
W	S24	S19	W

CORNER MONUMENT (OC ON
IP) AND ACCESSORIES
AS NOTED ON HOFFINE
9/17/02 REPORT FOUND
UNDESTURBED - DISTANCES
TO IRON ROD R1 AND
21" DAIL STUMP BT1
CHECKED WELL WITH REGRD.
BLK IP LOCATION WAS
REFERENCED THEN RESET
WITH TOP OF CAP 1 FOOT
BELOW SURFACE. NO NEW
REFERENCES WERE TIED
(OULR) S.S. FILE NO 64/34-34

WHOLE PIECES OF BROKEN

METAL FENCE POSTS FOUND

WITH THE CORNER

MONUMENT WERE REMOVED

FROM LOCATION AND

DEPOSITED SOUTH OF

CORNER LOCATION IN

R/W FENCE OWNERS

REQUESTED THIS MONUMENT

BE REPOSITIONED AS

IT INTERFERES WITH

HAYING.)

Ed Mow

STEVE FLAUSÉ

66/34-3A