

12-18-02 FILED DEC 20 2002 P1 # 045060

T265. R3W

ESE COR DLC 45

RANDALL W SMITH STEPHEN J FLAUS
FP 1966 DCSO BRASS CAP / IRON PIPE
PROTRUDS 7" OUT OF GROUND

- 6" NOW 10" DIA DOWN AND ROTTING
W/OAK WITH A PREVIOUSLY OPENED
UNHEALED BLAZE NO MARK
FOUND BEARS N40°W 15.2 FT
TO ROOT HOLE (OBT)

- ORIG SW BT NOW GONE

- 12" NOW 13" DIA. W/OAK WITH A
FULLY HEALED BLAZE, BEARS 58°W,
5.9 FT (1966)

12" NOW 20" DIA. 2 FT HIGH D/FIR
STUMP WITH A FULLY HEALED BLAZE
BEARS S67°E, 23.1 FT (1966)

NEW

- 13" DIA. D/FIR DOUBLE BLAZED AND
SCRIBED "ESE DLC 45CS BT" BEARS
S26½°E, 22.0 FT

- 7" DIA. W/OAK DOUBLE BLAZED AND
SCRIBED "ESE DLC 45CS BT" BEARS
N26°W, 1.0 FT

- 10" DIA. W/OAK DOUBLE BLAZED AND
SCRIBED "ESE DLC 45CS BT" BEARS
N55½°E, 13.2 FT

COMPASS DECL. 17½°E

✓ INT L DLC 45 FOUND OK

✓ NE COR DLC 45 NOT FOUND

✓ SSE COR DLC 45 NOT FOUND

ESE COR DLC 40 NOT FOUND