

6-4-03 FILED JUL 10 2003 P1 # 100700

T235 R5W NW COR SEC 6

RANDALL W SMITH STEPHEN J FLAUSCH

FO 1943 BLM BRASS CAP

IRON PIPE, PROTRUDES 8" OUT
OF GROUND- 11" NOW REMAINS OF ROTTED TO
GROUND D. FIR BEARS S68 1/2° W
24.4 FT OBT

SE OBT GONE

- 9" 1 FT HIGH ROTTED 10" FIR
STUMP NO MARK FOUND BEARS
S29° E 68.0 FT (1943)- 6" NOW 2 1/2" DIA W. FIR NO
BLAZE VISIBLE BEARS S11° W,
58.7 FT (1943) NOTE AS
GONE IN 1965 OCSO RENEWAL- 14" NOW 29" DIA W. FIR WITH A
FULLY HEALED DOUBLE BLAZE,
BEARS S84° E, 93.0 FT (1965)- 7" NOW 21" DIA D. FIR WITH A
FULLY HEALED DOUBLE BLAZE,
BEARS S70° W, 34.4 FT. (1965)NEW 12" DIA W. FIR DOUBLE BLAZED
AND SCRIBED "T235 R5W S6 (CS BT"
BEARS S28 1/2° E, 52.8 FT

PH # 100-1161

(ON BACK)
C.S. File No 66/58-10A

CORNER LIES AT THE
INTERSECTION OF A 3WAY
FENCE CORNER OLD
FENCE RUNS E-W AND
A S'LY FENCE LINE THATS
MOSTLY DOWN HAS A BEARING
OF S19°E. OLD NORTH RUNNING
FENCE LINE GOES FROM
E-W FENCE LINE 64 FT
WEST OF CORNER

UNABLE TO GET A GIS
POSITION

66/58-10B