

6-19-03 FILED JUL 10 2003 P1#140700

T2RS RSW N. 1/4 SEC 6 ONLY

RANDALL W SMITH STEPHEN J FLAUSÉ

FA 1958 DC50 BRASS CAP / IRON
PIPE PROTRUDES 15" OUT OF GROUND
IN E-W FENCE LINE.

- 16" NOW 30" DIA DOWN AND ROTTED
B. OAK SHOWING SIGNS OF BEING
PREVIOUSLY OPENED, NO SCRIBE
VISIBLE, ROOT HOLE AGREES
WELL WITH RECORD S89 1/4° E,
387.2 FT (OBTJ)

- ORIG. D. FIR BT NOT LOOKED FOR
AS IT WAS A ROTTED STUMP IN
1958

- 3" ? NOW 22" DIA W. OAK NU
BLAZE VISIBLE BEARS S65° E,
49.2 FT (1958)

NEW

23" DIA. W. OAK (N 1/4 SEC 31 BT)

WITH SW'ly BLAZE SCRIBED IN
1958, BEARS N 4 1/2° E, 256.5 FT

1958 DC50 BC/1P S 1/4 SEC 31
BEARS N 89 1/4° W, 337.0 FT

C.S. File No 66/58-15A

(ON BACK)

CORNER IS APPROX
45 FT WEST OF AN OLD
4-WAY FENCE CORNER

COMPASS DUELY $174\frac{1}{2}^{\circ}$ W

615

POB 24 18 A

PHOT 100 - 1165

66/58-15B

R062418A.asc

Approximate 1927 coordinate and geodetic
values determined using hand held trimble explorer
3 data collector/ not survey grade.

Point Name:

NQ T23SR5W S6 ONLY

GeoExplorer 3
1.011718

R062418A.cor 128 3.5
GPS TIME: 06/24/03 07:03:26pm
N 719547.3 E 1249235.5
LAT. 43 36 22.19 + LONG. 123 20 06.25 -
APPROX. MSL HEIGHT: 445.737

66/58-15c