

DEC. 17° EAST
S.J. FLAUSE AND J. PIKE
7/17/03

PG. 1 OF 2

PI# 140560

T32S R04W CN 1/16 SEC. 7

FIND: MONUMENT CALLED FOR IN 1971 BLM

FILED MAR 8 2004

SURVEY MISSING; ROAD RECON-
STRUCTION AND DRIVEWAY EXCA-
VATION HAVE DISTURBED AREA.

A.D. FIR 6" NOW 22" BEARS
S04°2'W, 157±' (RECORD) FHSB

A.D. FIR 26" NOW 40" BEARS
N03°1/2'W, 76±' (RECORD) FHSB

NEW: TIE IN 3 NEARBY ENCL. PROPERTY
CORNERS.

C.S. File No 67/61A

① A 5/8" I.R. FIRMLY SET APPROX. 1"
BELOW GROUND, BEARS S01°E, 24±'
FROM M50-39. (JUST NORTH OF FENCE COR.)
(FNC'S RUNNING SOUTH AND SW)

② A 5/8" I.R. FIRMLY SET APPROX 3"
BELOW GROUND, BEARS S56°1/2'W, 250±'
FROM M50-39. (≈ 3' SOUTH OF ROAD R/W FNC.)
IN YARD AT 1121 YEUST RD.

③ A 1" O.D. GALVANIZED I.P.
PROTRUDES APPROX 13" ABOVE GROUND TOP LEANS E'LY,
BEARS N01°W, 42±' FROM CS 55/57A
(JUST EAST OF FNC'S RUNNING SW AND N.)

16. 2012

T325 R04-W CN 1/16 S7 CONT'D

NO PERMANENT MONUMENT IS
SET AT CN 1/16 LOCATION BECAUSE
POSITION FALLS IN A GRAVEL DRIVE-
WAY COVERING A SHALLOWLY
BURIED CULVERT

THE THREE FOUND MONUMENTS
FROM SURVEYS RECORDED IN
THE DC SO AS M50-39 AND C555/57A
NOW SERVE AS BEARING OBJECTS
TO THE 1/16 CORNER.

C.S. File No

67/6-1B