

DEC. 17° EAST  
S.N. FAUSE AND J. PIKE  
7/17/03

Pg. 1 of 2

PI# 140560

T32 S R04 W CN 1/16 SEC. 7

FND: MONUMENT CALLED FOR IN 1971 BLM

FILED MAR 8 2004

SURVEY MISSING; ROAD RECON-  
STRUCTION AND DRIVEWAY EXCA-  
VATION HAVE DISTURBED AREA.

A D. FIR 6" NOW 22" BEARS

S04°2'W, 157±' (RECORD) FHSB

A D. FIR 26" NOW 40" BEARS

N03°2'W, 76±' (RECORD) FHSB

NEW: TIE IN 3 NEARBY FND. PROPERTY  
CORNERS.

① A 5/8" I.R. FIRMLY SET APPROX. 1"

BELOW GROUND, BEARS S01°E, 24±'

FROM M 50-39. (JUST NORTH OF FENCE COR.)  
(FENCE'S RUNNING SOUTH AND SW)

② A 5/8" I.R. FIRMLY SET APPROX 3"

BELOW GROUND, BEARS S56°2'W, 250±'

FROM M 50-39. (≈ 3' SOUTH OF ROAD R/W FENCE)  
IN YARD AT 1121 YEUST RD.

③ A 1" O.D. GALVANIZED I.P.

PROTRUDES APPROX 13" ABOVE GROUND, TOP LEANS ELY,  
BEARS N01°W, 42±' FROM CS 55/57A  
(JUST EAST OF FENCE'S RUNNING SW AND N.)

C.S. File No

67/61A

16. 2012

T325 R04-W CN 1/16 S7 CONT b

NO PERMANENT MONUMENT IS  
SET AT CN 1/16 LOCATION BECAUSE  
POSITION FALLS IN A GRAVEL DRIVE-  
WAY COVERING A SHALLOWLY  
BURIED CULVERT

THE THREE FOUND MONUMENTS  
FROM SURVEYS RECORDED IN  
THE DC SO AS M50-39 AND CS55/57A  
NOW SERVE AS BEARING OBJECTS  
TO THE 1/16 CORNER.

C.S. File No

67/6-1B