

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 305 Range 5W Sec. 7

County DOUGLAS

Date: 6/28/2005 By: JC

This survey consists of:

State OR

Date 6-14-2005

No. 140500

Map:

Number:

Corner Designation

Corner Rpt: 67/10-30

$\frac{1}{4}$ S 7
S 18

DOUGLAS COUNTY SURVEYOR

Condition Report

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals RICHARDSON 1948; BYRON 1963

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP WITH ILLEGIBLE MARKINGS 9" BELOW GROUND.

ILLEGIBLE

Accessories Found:

14" Now 24" D.A. W. OAK, FULLY HEALED DOUBLE BLAZE VISIBLE BEARS N 57 1/2° W, 24.3 FT. (REC. N 56° W, 24.3 FT.) 1948 BT

12" Now 20" D.A. W. OAK, FULLY HEALED DOUBLE BLAZE VISIBLE BEARS S 25° W, 124.5 FT. (AGREES W/ REC.) 1963 BT

