

FILED

Date: 10-24-2005 By: JC

This survey consists of:

GOVERNMENT CORNER RESTORATION FORM

Township 30 S Range 4 W Sec. 8

County DOUGLAS

State OR

Date 9-14-05

No. 039120

Map: _____
Narrative: _____

Corner Npt: 67/13-8

Corner Designation

DOUGLAS COUNTY
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

NE COR. CHAPMAN DLC 43

MONUMENT DETAIL

Previous Renewals

Monument(s) Found: (Condition and Source)

3" BRASS CAP. MARKINGS ARE ILLEGIBLE. LIES SLIGHTLY UNDER EDGE OF ROAD 8" BELOW SURFACE OF ASPHALT. 13 FT. FROM CENTERLINE.

Accessories Found:

MEAS. 16" MAPLE NOW 17" AT 2 FT. ABOVE GROUND (SPLIT TRUNK) HIGH & LOW FULLY HEALED BLAZES VISIBLE ON MOST WESTERLY TRUNK BEARS N 56 3/4° E, 120^B FT. (REC. N 54° E, 120 1/2 FT.) 1994 BT

FIR SNAG NOW TIPPED OUT STUMP (REC. N 55 1/4° E, 126 2/3 FT.) 1940 BT

81" MAPLE NOW 90" NO MARKINGS EVIDENT. TREE IS NOW MULTI TRUNKED & SPLIT DOWN THE MIDDLE AND IS TO BE REMOVED IN FUTURE. BEARS S 2 3/4° W, 87 1/2 FT. (REC. S 2 3/4° W, 86 2 FT.) 1940 BT

3 1/2" BRASS DISC SET IN CONCRETE "US COAST & GEODETIC SURVEY BENCHMARK U499 1949" BEARS S 60° W, 33^B FT. (AGREES WITH RECORD)

C.S. File No 67/13-8

