

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 255 Range 7W Sec. 34

County DOUGLAS

Date: 4/6/2007 By: X

This survey consists of:

State OREGON Date 3-15-2007

No. 440100

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Designation

Corner Rpt: 67/21-21

SOUTH  $\frac{1}{4}$  COR. SEC. 34

- DOUGLAS COUNTY**  
**SURVEYOR**
- Condition Report Only
  - Not Found
  - Renewed
  - Unrecorded
  - Surveyed In
  - Referenced Out

MONUMENT DETAIL

Previous Renewals 1975

Monument(s) Found: (Condition and Source)

BRASS CAP 10" BELOW SURFACE  
 IN PASTURE. COULD NOT CHECK  
 SIZE OR MARKINGS AS HOLE FILLED  
 WITH WATER.

Accessories Found:

14" TWIN CEDAR NOW 33" DIA SINGLE TRUNK I. CEDAR EVID. OF  
 BROKEN OFF TRUNK TO WEST. NO BLAZE OR MARKS  
 VISIBLE, BEARS N 23 1/2° E, 391.1 FT. (AGREES W/REC.) 1975 BT

22" NOW 36" DIA. X 20" TALL D. FIR STUMP EVID. OF LOW HEALED BLAZE.  
 STUMP IS JUST STARTING TO ROT, BEARS S 6° E, 128.7 FT.  
 (AGREES W/REC.) 1975 BT

C.S. File No 67/21-21

