

GOVERNMENT CORNER RESTORATION FORM

FILED

Date: FEB 9 2009 By: JC

Township 27S Range 7W Sec. 10


County DOUGLAS This survey consists of:

State OR Date 2-2-2009

No. 5005 Narrative:

Corner Rpt: 67/28-11

Corner Designation



DOUGLAS COUNTY

Surveyor's Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1960, 1977

Monument(s) Found: (Condition and Source)

FD BRASS CAP / IRON PIPE
 LFT UNDER GROUND IN OPEN
 PASTURE. UNABLE TO VISUALLY
 SEE BC/IP AS GROUND SATURATED
 WITH WATER. FELT TOP OF
 BC/IP. FENCE POST ALONG
 SIDE REMOVED AT OWNER'S
 REQUEST. 1960

N/A

Accessories Found:

12" NOW DOUBLE TRUNKED W. OAK WITH A FULLY
 HEALED SINGLE BLAZE ON 16" DIA. NORTHERLY TRUNK
 BEARS N 46 1/2° E, 147.6 (AGREES WITH 1960 REC.) 1960 BT

8" NOW 16" DIA W. OAK WITH A FULLY HEALED SINGLE
 BLAZE BEARS N 86° E, 179.0 FT (AGREES WITH
 1960 REC.) 1960

5/8" I.R. FD, 2" BELOW GROUND WITH OUT A CAP
 IS FOUND 6' NORTHERLY OF NEW FENCE LINE
 BEARS N 23 1/2° E, 136.0 FT (REC N 24 1/2° E, 136.0 FT) 1970

