

GOVERNMENT CORNER RESTORATION FORM

Date: 3/9/2009 By: JC

Township 22S Range 4W Sec. 34 County DOUGLAS This survey consists of: _____
Map: _____

State OR Date 2-27-2009 No. 500140 Narrative: _____

Corner Rpt: 67/28-21

Corner Designation

1/4 S34 | S35

DOUGLAS COUNTY

SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals 1964

Monument(s) Found: (Condition and Source)

FD 2 1/2" O.D. BRASS CAPON
A 1 1/2" O.D. IRON PIPE, PROTRUDING
4" OUT OF GROUND. (1964)

2" DIA IRON PIPE PROTRUDING
12" OUT OF GROUND BEARS
0.5 FT SW OF BC/IP (1944)

COUNTY SURVEYOR OFFICE

T 22S R 4W

1/4 S34/S34

1964

Accessories Found:

15" Now 32" DIA D.FIR WITH A FULLY HEALED
BLAZE, BEARS S 20° E, 8.7 FT (AGREES WITH REC) 1964

32" Now 36" DIA 4 FT HIGH D.FIR STUMP
WITH A FULLY HEALED BLAZE, BEARS N 42° W, 14.3 FT
(AGREES WITH REC) 1964

24" ROTTED FIR STUMP BEARS N 69° E 36.2 FT
(AGREES WITH REC)

