

GOVERNMENT CORNER RESTORATION FORM

Date: 3/1/2010 By: JC

Township 30S Range 4N Sec. 25


County DOUGLAS This survey consists of:
Map: _____

State OR Date 2-17-2010

No. 051010 Narrative: _____

Corner Rpt: 67/31-4

Corner Designation



DOUGLAS COUNTY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1889, 1930, 1963, 1982

Monument(s) Found: (Condition and Source)

FD BLM BRASS CAP IRON
PIPE IN LARGE ROOT OF AN
ORIG. BT, BT NOW 20 HIGHER
SNAG WITH A FULLY HEALED
BLAZE FACING BLM BC/IP. OLD
BARK SCRIBING FOUND ON
NORTH TRUNK "S 2 T 30 S
RW 30 1"

Accessories Found:

RE TAG 1930 TAN OAK WITH HEALED BLAZE
AND 1963 MAPLE
1963 I.R. FOUND 2 1/2 FT BELOW GROUND.

MONUMENT DETAIL

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

N/A

N/A

New Accessories

N/A

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LIES ON EASTERN
BANK OF SOUTH UMPQUA
RIVER

Comp. Declin. $16^{\circ}12' E$
Agency DCS
Party Chief RANDY SMITH
Notekeeper STEVE FLAUSC
Witnesses _____

Address

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Randy Smith

OREGON
JULY 25, 1990
RANDALL W. SMITH
2469

*Revised
6-30-10*